

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2017 Levee Inspection Results

Reclamation District No. 2085 Kasson

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Reclamation District No. 2085 Kasson

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Left	5.29
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2017 - 4/20/2017			
DWR Inspector	Maksim Khashchuk			
Accompanied By	Ralph Timan RD2085			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD2085_01_s_2013_7				
Comment Code					
Inspector Comment					
The O&M Manual is available at the office.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD2085_01_s_2013_9				
Comment Code					
Inspector Comment					
Flood fighting supplies are available at the River Club.					

No Photos

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_RD2085_01_s_2013_14				
Comment Code					
Inspector Comment					
The LMA has a flood fighting plan and training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.12	Rating **	A/W	Issue No.	19
LM End	0.47	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.719052 °	37.723246 °
				-121.302928 °	-121.299492 °
DWR ID	DWR_RD2085_01_f_2015_19				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					
Disking on the levee shoulder. Make sure the water drains evenly to the slopes.					

Photo 1 of 1 : SP_2017_RD2085_113_19_20170407_00010.jpg



View of the disking on the levee crown shoulder.

LM Start	0.46	Rating **	U	Issue No.	54
LM End	0.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.723182 °	37.723383 °
				-121.299549 °	-121.299370 °
DWR ID	DWR_RD2085_01_s_2017_54				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_54_20170421_00069.jpg



View of the vegetation on the landside levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.53	Rating **	A/W	Issue No.	55
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.723415 °	37.723415 °
				-121.298596 °	-121.298596 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47170
DS_ID:20677
EP_NO: N/A
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: Pipe has been removed by LMA. Previous: Pipe abandoned. Erosion around pipe on WS slope. Pipe severely corroded. Pier badly damaged.
FIELD_STRUCT_DESC: *REMOVED* 14-inch steel stormdrain pipe through the levee 4.5 feet below crown. Pump on pile structure in ditch on the landward side. Siphon breaker in corrugated metal riser unit on the waterward shoulder. Originally included in the 1968 O&M manual. Pipe removed by LMA. Permit Application No. T2013179 submitted to CVFPB. Permit was not needed per CVFPB review.
FS Date: 9/5/2013

LM Start	0.53	Rating **	A/W	Issue No.	55 (cont)
LM End	0.53	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_47170_62262.jpg



Pipe on WS with erosion into levee slope.

Photo 2 of 3 : UCIP_SP_2017_47170_62261.jpg



Pipe at WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.53	Rating **	A/W	Issue No.	55 (cont)	
LM End	0.53	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			37.723415 °		37.723415 °
				-121.298596 °		-121.298596 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:47170						
DS_ID:20677						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments: Pipe has been removed by LMA.Previous:Pipe abandoned. Erosion around pipe on WS slope. Pipe severely corroded. Pier badly damaged.						
FIELD_STRUCT_DESC: *REMOVED* 14-inch steel stormdrain pipe through the levee 4.5 feet below crown. Pump on pile structure in ditch on the landward side. Siphon breaker in corrugated metal riser unit on the waterward shoulder. Originally included in the 1968 O&M manual. Pipe removed by LMA. Permit Application No. T2013179 submitted to CVFPB. Permit was not needed per CVFPB review.						
FS Date: 9/5/2013						

Photo 3 of 3 : UCIP_SP_2017_47170_62260.jpg



Siphon breaker in 24-inch CMP riser on WS shoulder. Filled with soil.

LM Start	0.70	Rating **	M	Issue No.	48
LM End	1.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.721939 °	37.717553 °
				-121.296102 °	-121.291828 °
DWR ID	DWR_RD2085_01_s_2017_48				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_48_20170421_00068.jpg



View of the vegetation on the landside levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.87	Rating **	M	Issue No.	53
LM End	0.87	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.720142 °	37.720142 °
				-121.294027 °	-121.294027 °
DWR ID	DWR_RD2085_01_s_2017_53				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_53_20170421_00070.jpg



View of the tire rut on the waterside levee shoulder.

LM Start	1.18	Rating **	M	Issue No.	47
LM End	1.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.716216 °	37.716216 °
				-121.291387 °	-121.291387 °
DWR ID	DWR_RD2085_01_s_2017_47				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Vehicle ruts on the levee slope and toe.					

Photo 1 of 1 : SP_2017_RD2085_113_47_20170421_00067.jpg



View of the disturbed landside levee slope.

LM Start	1.34	Rating **	M	Issue No.	6
LM End	1.38	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.714265 °	37.714056 °
				-121.289641 °	-121.289069 °
DWR ID	DWR_RD2085_01_s_2012_6				
Comment Code					
DT : Ditch					
Inspector Comment					
Drainage ditch at levee toe.					

Photo 1 of 1 : SP_2017_RD2085_113_6_20170407_00007.jpg



View of the ditch at the landside levee toe.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	1.35	Rating **	A/W	Issue No.	56
LM End	1.35	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.714409 °	37.714409 °
				-121.289479 °	-121.289479 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19384 DS_ID:20678 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 12-inch steel stormdrain pipe through the levee 3-feet below the crown. Pump mounted on pile structure in ditch on the landward side. Steel walkway with handrails to the pump structure. Gate valve and Siphon breaker in 12-inch steel riser unit on the waterward shoulder. Originally included in the 1968 O&M manual. (Permit No. 8189, 1972) FS Date: 9/5/2013					

LM Start	1.35	Rating **	A/W	Issue No.	56 (cont)
LM End	1.35	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_19384_32928.jpg



Pipe, siphon breaker, and gate valve on WS slope.

Photo 2 of 3 : UCIP_SP_2017_19384_32927.jpg



Pump on metal pier on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	1.35	Rating **	A/W	Issue No.	56 (cont)	
LM End	1.35	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			37.714409 °		37.714409 °
				-121.289479 °		-121.289479 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19384						
DS_ID:20678						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 12-inch steel stormdrain pipe through the levee 3-feet below the crown. Pump mounted on pile structure in ditch on the landward side. Steel walkway with handrails to the pump structure. Gate valve and Siphon breaker in 12-inch steel riser unit on the waterward shoulder. Originally included in the 1968 O&M manual. (Permit No. 8189, 1972)						
FS Date: 9/5/2013						

Photo 3 of 3 : UCIP_SP_2017_19384_32926.jpg



Pipe, siphon breaker, and gate valve on WS slope.

LM Start	1.35	Rating **	M	Issue No.	57
LM End	1.35	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.714404 °	37.714404 °
				-121.289469 °	-121.289469 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:22285 DS_ID:24055 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No permit identified for this modified crossing. FIELD_STRUCT_DESC: 12-inch steel pipe through the levee 3-feet below the crown. Pump mounted on pile structure in ditch on the landward side. Siphon breaker in 12-inch steel riser unit and a gatevalve on the waterward shoulder. (Permit No. 8189, 1972) FS Date: 9/10/2013					

Photo 1 of 3 : UCIP_SP_2017_22285_38010.jpg



Pipe, gate valve, and siphon breaker visible on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	1.35	Rating **	M	Issue No.	57 (cont)	
LM End	1.35	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			37.714404 °	37.714404 °	
				-121.289469 °	-121.289469 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:22285						
DS_ID:24055						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: No permit identified for this modified crossing.						
FIELD_STRUCT_DESC: 12-inch steel pipe through the levee 3-feet						
below the crown. Pump mounted on pile structure in ditch on the						
landward side. Siphon breaker in 12-inch steel riser unit and a						
gatevalve on the waterward shoulder. (Permit No. 8189, 1972)						
FS Date: 9/10/2013						

Photo 2 of 3 : UCIP_SP_2017_22285_38009.jpg



Pipe, pump, and walkway visible on LS toe.

LM Start	1.35	Rating **	M	Issue No.	57 (cont)
LM End	1.35	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_SP_2017_22285_38008.jpg



Pipe, gate valve, and siphon breaker visible on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	1.41	Rating **	M	Issue No.	58
LM End	1.41	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.714049 °	37.714049 °
				-121.288426 °	-121.288426 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41351					
DS_ID:20679					
EP_NO: 3975					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Pipe abandoned and should be done so properly.					
Large hole in ground over pipe on WS berm. Pipe rusted through on					
WS at river bank. No connection to pump on LS toe.					
FIELD_STRUCT_DESC: *ABANDONED* 10-inch steel stormdrain pipe					
through the levee 4-feet below the crown. Steel plate over pipe end at					
pump station on LS toe. Siphon breaker in 24-inch corrugated metal					
riser unit on the waterward shoulder (Permit No. 3975, 1962). Originally					
included in the 1968 O&M manual.					
FS Date: 9/5/2013					

Photo 1 of 3 : UCIP_SP_2017_41351_62268.jpg



Siphon breaker in 24-inch CMP riser on WS shoulder.

LM Start	1.41	Rating **	M	Issue No.	58 (cont)
LM End	1.41	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_41351_62267.jpg



Pipe visible at bottom of ditch on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	1.41	Rating **	M	Issue No.	58 (cont)
LM End	1.41	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.714049 °	37.714049 °
				-121.288426 °	-121.288426 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41351 DS_ID:20679 EP_NO: 3975 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe abandoned and should be done so properly. Large hole in ground over pipe on WS berm. Pipe rusted through on WS at river bank. No connection to pump on LS toe. FIELD_STRUCT_DESC: *ABANDONED* 10-inch steel stormdrain pipe through the levee 4-feet below the crown. Steel plate over pipe end at pump station on LS toe. Siphon breaker in 24-inch corrugated metal riser unit on the waterward shoulder (Permit No. 3975, 1962). Originally included in the 1968 O&M manual. FS Date: 9/5/2013					

Photo 3 of 3 : UCIP_SP_2017_41351_62266.jpg



Pipe visible at bottom of ditch on LS toe.

LM Start	1.63	Rating **	M	Issue No.	43
LM End	1.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.712676 °	37.712676 °
				-121.284732 °	-121.284732 °
DWR ID	DWR_RD2085_01_s_2017_43				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	1.79	Rating **	M	Issue No.	39
LM End	1.79	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.711456 °	37.711456 °
				-121.282397 °	-121.282397 °
DWR ID	DWR_RD2085_01_s_2016_39				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
LMA has bait stations on the levee.					

Photo 1 of 1 : SP_2017_RD2085_113_39_20170407_00022.jpg



View of the rodent burrows on the landside levee slope.

LM Start	2.04	Rating **	M	Issue No.	59
LM End	2.04	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.708826 °	37.708826 °
				-121.279271 °	-121.279271 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19423 DS_ID:20681 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pipe is abandoned and should be done so properly. FIELD_STRUCT_DESC: 1 of 2: 10-inch pipe through the levee 2.0-feet below the crown. Pump mounted on pile structure in the river. Siphon breaker in 24-inch CMP riser on the LS slope. Power pole on LS toe. Wooden stairs and walkway from the berm to the pump structure. Originally included in the 1968 O&M manual. FS Date: 9/5/2013 8:22:24 AM					

Photo 1 of 3 : UCIP_SP_2017_19423_32962.jpg



Siphon breaker in 24-inch CMP riser on LS slope. Possible gate valve at end of concrete channel on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	2.04	Rating **	M	Issue No.	59 (cont)	
LM End	2.04	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			37.708826 °		37.708826 °
				-121.279271 °		-121.279271 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19423 DS_ID:20681 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pipe is abandoned and should be done so properly. FIELD_STRUCT_DESC: 1 of 2: 10-inch pipe through the levee 2.0-feet below the crown. Pump mounted on pile structure in the river. Siphon breaker in 24-inch CMP riser on the LS slope. Power pole on LS toe. Wooden stairs and walkway from the berm to the pump structure. Originally included in the 1968 O&M manual. FS Date: 9/5/2013 8:22:24 AM						

LM Start	2.04	Rating **	M	Issue No.	59 (cont)
LM End	2.04	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_19423_32961.jpg



Pipe cut at wooden pier. No pump on end of pier for this pipe.

Photo 3 of 3 : UCIP_SP_2017_19423_32960.jpg



Power pole on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	2.05	Rating **	M	Issue No.	18
LM End	2.51	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.708737 °	37.703893 °
				-121.279087 °	-121.274605 °
DWR ID	DWR_RD2085_01_s_2012_18				
Comment Code					
DT : Ditch					
Inspector Comment					
Concrete-lined ditch near levee toe.					

No Photos

LM Start	2.56	Rating **	M	Issue No.	1
LM End	2.58	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.703094 °	37.703094 °
				121.274894 °	121.274894 °
DWR ID	DWR_RD2085_01_s_2017_1				
Comment Code					
Inspector Comment					
07/08/2016: No significant change observed.					
09/10/2015: No significant change observed. Signs of animal activity are present.					
09/10/2014: No significant change observed.					
09/20/2013: No significant change in erosion observed. More vegetation at the site.					
12/04/2012: The erosion has progressed remarkably toward levee, extended to the up-and downstream of the original pocket erosion. Trees and dense bush are present at the site. Animal burrow holes are visible, and possibly can cause seepage.					
09/22/2010: No significant change observed. There is little visibility due to seasonal grass on the berm and slope.					
08/18/2009: Site is located on berm; pocket erosion has developed; the site is covered in dense vegetation; there are several relief wells on the landside of the levee; site is Not Rated because berm width is greater than 30 feet; site should be monitored to keep track of erosion progress. [2016 Site ID:RD2085U01RM66.5]					

Photo 1 of 3 : SP_2017_RD2085_113_1_20170407_00001.jpg



Close view of the erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

Reclamation District No. 2085 Kasson

LM Start	2.56	Rating **	M	Issue No.	1 (cont)
LM End	2.58	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : SP_2017_RD2085_113_1_20170407_00002.jpg



Direct view of the erosion. Note the dense vegetation at the site.

Photo 3 of 3 : SP_2017_RD2085_113_1_20170407_00003.jpg



Close view of the erosion.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	2.58	Rating **	A/W	Issue No.	20
LM End	2.58	Issue Type +	Ob	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			37.702903 °	37.702903 °
				-121.274860 °	-121.274860 °
DWR ID	DWR_RD2085_01_s_2012_20				
Comment Code					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_20_20170407_00011.jpg



View of the underseepage relief wells at the landside levee toe.

LM Start	2.62	Rating **	M	Issue No.	41
LM End	3.37	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.702372 °	37.692697 °
				-121.275090 °	-121.278007 °
DWR ID	DWR_RD2085_01_s_2017_41				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_41_20170421_00066.jpg



View of the vegetation on the landside levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	2.82	Rating **	M	Issue No.	60
LM End	2.82	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.699698 °	37.699698 °
				-121.276325 °	-121.276325 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19431					
DS_ID:20688					
EP_NO: 16970					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: The wooden walkway on the WS slope is in disrepair.					
FIELD_STRUCT_DESC: 1 of 2: 14-inch steel irrigation pipe through the					
levee 2.0 feet below the crown. Pump on wooden pier at WS slope.					
Siphon breaker visible next to steel bollard on LS slope. Power pole on					
LS toe.					
FS Date: 9/5/2013					

Photo 1 of 3 : UCIP_SP_2017_19431_32983.jpg



Pump on Wooden pier at WS slope.

LM Start	2.82	Rating **	M	Issue No.	60 (cont)
LM End	2.82	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_19431_32982.jpg



Pipe visible under walkway on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	2.82	Rating **	M	Issue No.	60 (cont)	
LM End	2.82	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			37.699698 °	37.699698 °	
				-121.276325 °	-121.276325 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19431						
DS_ID:20688						
EP_NO: 16970						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: The wooden walkway on the WS slope is in disrepair.						
FIELD_STRUCT_DESC: 1 of 2: 14-inch steel irrigation pipe through the						
levee 2.0 feet below the crown. Pump on wooden pier at WS slope.						
Siphon breaker visible next to steel bollard on LS slope. Power pole on						
LS toe.						
FS Date: 9/5/2013						

Photo 3 of 3 : UCIP_SP_2017_19431_32981.jpg



Power pole on LS toe with possible PVC riser.

LM Start	2.90	Rating **	A/W	Issue No.	21
LM End	2.90	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.698700 °	37.698700 °
				-121.277199 °	-121.277199 °
DWR ID	DWR_RD2085_01_f_2015_21				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
This area should be monitored for possible rodent activity.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.27	Rating **	M	Issue No.	42
LM End	3.27	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.694085 °	37.694085 °
				-121.277378 °	-121.277378 °
DWR ID	DWR_RD2085_01_s_2017_42				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	3.30	Rating **	M	Issue No.	61
LM End	3.30	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.693618 °	37.693618 °
				-121.277639 °	-121.277639 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19433 DS_ID:20693 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe appears abandoned and should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 10-inch steel stormdrain pipe through the levee 4.0-feet below the crown. T-post marks location of Pipe at LS toe. Steel plate welded over pipe on WS slope. Asbuilts available DWG 7-4-1685. Originally included in the 1968 O&M manual. FS Date: 9/5/2013					

Photo 1 of 3 : UCIP_SP_2017_19433_32990.jpg



T-post marking pipe end on LS toe. 10-inch pipe debris on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.30	Rating **	M	Issue No.	61 (cont)	
LM End	3.30	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			37.693618 °	37.693618 °	
				-121.277639 °	-121.277639 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19433 DS_ID:20693 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe appears abandoned and should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 10-inch steel stormdrain pipe through the levee 4.0-feet below the crown. T-post marks location of Pipe at LS toe. Steel plate welded over pipe on WS slope. Asbuilts available DWG 7-4-1685. Originally included in the 1968 O&M manual. FS Date: 9/5/2013						

Photo 2 of 3 : UCIP_SP_2017_19433_32989.jpg



Pipe visible on WS slope.

LM Start	3.30	Rating **	M	Issue No.	61 (cont)
LM End	3.30	Issue Type +	Ma	Location *	LS

Photo 3 of 3 : UCIP_SP_2017_19433_32988.jpg



Pipe visible on WS slope. Steel plate welded over end.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.34	Rating **	N	Issue No.	30
LM End	3.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.693019 °	37.693019 °
				-121.277892 °	-121.277892 °
DWR ID	DWR_RD2085_01_s_2014_30				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	3.42	Rating **	M	Issue No.	62
LM End	3.42	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.691966 °	37.691966 °
				-121.278122 °	-121.278122 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19435 DS_ID:20687 EP_NO: 16970 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 2 of 2: 10-inch steel stormdrain pipe through the levee 2-feet below the crown. Appears to connect to pump 150-feet off LS toe. Possible butterfly valve at LS toe. Vent on WS shoulder. Steel plate welded over pipe end on WS toe. FS Date: 9/5/2013					

Photo 1 of 3 : UCIP_SP_2017_19435_32993.jpg



Possible Butterfly valve at LS toe.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.42	Rating **	M	Issue No.	62 (cont)	
LM End	3.42	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			37.691966 °		37.691966 °
				-121.278122 °		-121.278122 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19435 DS_ID:20687 EP_NO: 16970 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 2 of 2: 10-inch steel stormdrain pipe through the levee 2-feet below the crown. Appears to connect to pump 150-feet off LS toe. Possible butterfly valve at LS toe. Vent on WS shoulder. Steel plate welded over pipe end on WS toe. FS Date: 9/5/2013						

LM Start	3.42	Rating **	M	Issue No.	62 (cont)
LM End	3.42	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_19435_32992.jpg



Possible connection at pump 150-feet off LS toe.

Photo 3 of 3 : UCIP_SP_2017_19435_32991.jpg



Vent on WS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.55	Rating **	A/W	Issue No.	44
LM End	3.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.690418 °	37.690418 °
				-121.276815 °	-121.276815 °
DWR ID	DWR_RD2085_01_s_2016_44				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
LMA has bait stations on the levee slope.					

No Photos

LM Start	3.57	Rating **	M	Issue No.	45
LM End	3.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.690161 °	37.690161 °
				-121.276543 °	-121.276543 °
DWR ID	DWR_RD2085_01_s_2016_45				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 2 : SP_2017_RD2085_113_45_20170407_00023.jpg



View of the rodent burrows on the landside levee slope. Fall 2016

LM Start	3.57	Rating **	M	Issue No.	45 (cont)
LM End	3.57	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2017_RD2085_113_45_20170407_00024.jpg



View of the rodent burrows on the landside levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.62	Rating **	A/W	Issue No.	2
LM End	3.75	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.688545 °	37.688545 °
				-121.276298 °	-121.276298 °
DWR ID	DWR_RD2085_01_s_2017_2				
Comment Code					
Inspector Comment					
07/08/2016: The erosion in the berm was found slightly progressed toward the levee toe. Signs of fresh erosion at the site are visible. 08/19/2015: No significant change observed. 07/17/2014: No significant change observed. 09/10/2013: No significant change observed. 12/04/2012: This site has been documented before, and a cost estimate to repair has been prepared dated 05/09/2010. The fresh cut shows the erosion is developing. The berm width is at least 42 feet. Sticks were placed at three locations along the river bank, with 3 sticks 5 feet apart at each location. [2016 Site ID:RD2085U01RM67.7]					

LM Start	3.62	Rating **	A/W	Issue No.	2 (cont)
LM End	3.75	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : SP_2017_RD2085_113_2_20170407_00004.jpg



View of the downstream end of the erosion.

Photo 2 of 3 : SP_2017_RD2085_113_2_20170407_00005.jpg



Close view of the erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.71	Rating **	A/W	Issue No.	25
LM End	3.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.688216 °	37.688216 °
				-121.276603 °	-121.276603 °
DWR ID	DWR_RD2085_01_f_2015_25				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Control levee access to prevent damage to levee slopes by vehicle.					

Photo 1 of 1 : SP_2017_RD2085_113_25_20170407_00012.jpg



View of the waterside levee slope damaged by vehicle.

LM Start	3.74	Rating **	A/W	Issue No.	26
LM End	3.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.687841 °	37.687841 °
				-121.276678 °	-121.276678 °
DWR ID	DWR_RD2085_01_f_2015_26				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Area should be maintained to prevent further levee damage.					

Photo 1 of 1 : SP_2017_RD2085_113_26_20170407_00013.jpg



View of the foot path on the levee slope.

LM Start	3.78	Rating **	M	Issue No.	46
LM End	3.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.687253 °	37.687253 °
				-121.276780 °	-121.276780 °
DWR ID	DWR_RD2085_01_s_2016_46				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_46_20170421_00065.jpg



View of the tire tracks on the levee slope.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.80	Rating **	A/W	Issue No.	63
LM End	3.80	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.686976 °	37.686976 °
				-121.276838 °	-121.276838 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19436 DS_ID:20683 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 30-inch Reinforced concrete box culvert stormdrain through the levee 12.0 feet below the crown. Slide gate in concrete riser unit on the waterward slope. Concrete "U" headwalls on both ends. Flap gate on the waterward end. Two concrete cutoff walls. Originally included in the 1968 O&M manual. FS Date: 9/5/2013 9:49:55 AM					

Photo 1 of 3 : UCIP_SP_2017_19436_32997.jpg



Slide gate in Concrete riser on WS shoulder.

LM Start	3.80	Rating **	A/W	Issue No.	63 (cont)
LM End	3.80	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_19436_32996.jpg



Concrete headwall off LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	3.80	Rating **	A/W	Issue No.	63 (cont)	
LM End	3.80	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			37.686976 °	37.686976 °	
				-121.276838 °	-121.276838 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19436						
DS_ID:20683						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 30-inch Reinforced concrete box culvert stormdrain through the levee 12.0 feet below the crown. Slide gate in concrete riser unit on the waterward slope. Concrete "U" headwalls on both ends. Flap gate on the waterward end. Two concrete cutoff walls. Originally included in the 1968 O&M manual.						
FS Date: 9/5/2013 9:49:55 AM						

Photo 3 of 3 : UCIP_SP_2017_19436_32995.jpg



Concrete U-shaped headwall on WS slope.

LM Start	3.86	Rating **	M	Issue No.	36
LM End	3.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.686059 °	37.685340 °
				-121.276745 °	-121.276594 °
DWR ID	DWR_RD2085_01_f_2016_36				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_36_20170407_00021.jpg



View of the rodent holes on the levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	4.03	Rating **	M	Issue No.	64
LM End	4.03	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.683642 °	37.683642 °
				-121.275792 °	-121.275792 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:19443					
DS_ID:20684					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: This pipe appears abandoned and should be done so properly.					
FIELD_STRUCT_DESC: 6-inch steel irrigation pipe through the levee 4.0-feet below the crown. Pump house on the waterward berm. Siphon breaker in 24-inch corrugated metal riser unit on the landside shoulder. Vent on WS toe. 2-inch galvanized iron electrical conduit at same location. Originally included in the 1968 O&M manual.					
FS Date: 9/5/2013					

Photo 1 of 3 : UCIP_SP_2017_19443_33002.jpg



Pumphouse and pipe visible on WS toe.

LM Start	4.03	Rating **	M	Issue No.	64 (cont)
LM End	4.03	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_19443_33001.jpg



Siphon breaker on vent in 24-inch CMP riser on LS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	4.03	Rating **	M	Issue No.	64 (cont)	
LM End	4.03	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			37.683642 °	37.683642 °	
				-121.275792 °	-121.275792 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:19443 DS_ID:20684 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pipe appears abandoned and should be done so properly. FIELD_STRUCT_DESC: 6-inch steel irrigation pipe through the levee 4.0-feet below the crown. Pump house on the waterward berm. Siphon breaker in 24-inch corrugated metal riser unit on the landside shoulder. Vent on WS toe. 2-inch galvanized iron electrical conduit at same location. Originally included in the 1968 O&M manual. FS Date: 9/5/2013						

Photo 3 of 3 : UCIP_SP_2017_19443_33000.jpg



Pump missing from pipe in pumphouse on WS toe.

LM Start	4.15	Rating **	M	Issue No.	34
LM End	4.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.682495 °	37.682495 °
				-121.274169 °	-121.274169 °
DWR ID	DWR_RD2085_01_f_2016_34				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_34_20170407_00020.jpg



View of the rodent holes on the levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	4.40	Rating **	M	Issue No.	33
LM End	4.45	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.681863 °	37.681640 °
				-121.269856 °	-121.269046 °
DWR ID	DWR_RD2085_01_s_2012_33				
Comment Code					
V6 : Landscaping					
Inspector Comment					

Photo 1 of 2 : SP_2017_RD2085_113_33_20170407_00018.jpg



Updated photo of encroachments on landside toe.

LM Start	4.40	Rating **	M	Issue No.	33 (cont)
LM End	4.45	Issue Type +	En	Location *	LS

Photo 2 of 2 : SP_2017_RD2085_113_33_20170407_00019.jpg



View of the landscaping at the landside levee slope.

LM Start	4.43	Rating **	M	Issue No.	27
LM End	4.43	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.681710 °	37.681710 °
				-121.269290 °	-121.269290 °
DWR ID	DWR_RD2085_01_f_2015_27				
Comment Code					
MA : Material					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_27_20170407_00014.jpg



View of the material stored at the landside levee toe.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	4.46	Rating **	N	Issue No.	32
LM End	4.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.681605 °	37.681605 °
				-121.268882 °	-121.268882 °
DWR ID	DWR_RD2085_01_s_2012_32				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_32_20170407_00017.jpg



11/03/2011 Large stump on landside slope.

LM Start	4.49	Rating **	U	Issue No.	28
LM End	4.49	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.681453 °	37.681453 °
				-121.268327 °	-121.268327 °
DWR ID	DWR_RD2085_01_f_2015_28				
Comment Code					
V6 : Landscaping					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_28_20170407_00015.jpg



View of the unmaintained vegetation at the landside levee toe.

LM Start	4.59	Rating **	M	Issue No.	17
LM End	4.59	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.681158 °	37.681158 °
				-121.266587 °	-121.266587 °
DWR ID	DWR_RD2085_01_f_2013_17				
Comment Code					
FW : Firewood					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_17_20170421_00064.jpg



View of the firewood and debris stored at the landside levee toe.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	4.63	Rating **	M	Issue No.	40
LM End	4.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.680963 °	37.678389 °
				-121.265844 °	-121.266341 °
DWR ID	DWR_RD2085_01_s_2017_40				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_40_20170421_00063.jpg



View of the vegetation on the landside levee slope.

LM Start	5.05	Rating **	C	Issue No.	51
LM End	5.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.677691 °	37.677691 °
				-121.269236 °	-121.269236 °
DWR ID	DWR_RD2085_01_s_2016_51				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

No Photos

LM Start	5.20	Rating **	M	Issue No.	52
LM End	5.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.675620 °	37.675620 °
				-121.269359 °	-121.269359 °
DWR ID	DWR_RD2085_01_s_2016_52				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_52_20170407_00026.jpg



View of the tire tracks on the levee slope.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	5.22	Rating **	A/W	Issue No.	65
LM End	5.22	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			37.675271 °	37.675271 °
				-121.269281 °	-121.269281 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23060					
DS_ID:20686					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 30-inch reinforced concrete stormdrain pipe					
through the levee 10.0 feet below the crown. Concrete "U" shaped					
headwall on the waterward end. Two corrugated metal cutoff walls. Flap					
gate on the waterward end. Originally included in the 1968 O&M					
manual.					
FS Date: 9/5/2013					

LM Start	5.22	Rating **	A/W	Issue No.	65 (cont)
LM End	5.22	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_23060_39184.jpg



Cuts in pavement off LS toe good indicator of pipe location.

Photo 2 of 3 : UCIP_SP_2017_23060_39183.jpg



Concrete U-shaped headwall visible on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	5.22	Rating **	A/W	Issue No.	65 (cont)	
LM End	5.22	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			37.675271 °		37.675271 °
				-121.269281 °		-121.269281 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23060						
DS_ID:20686						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 30-inch reinforced concrete stormdrain pipe						
through the levee 10.0 feet below the crown. Concrete "U" shaped						
headwall on the waterward end. Two corrugated metal cutoff walls. Flap						
gate on the waterward end. Originally included in the 1968 O&M						
manual.						
FS Date: 9/5/2013						

Photo 3 of 3 : UCIP_SP_2017_23060_39182.jpg



Concrete U-shaped headwall and flapgate visible on WS toe.

LM Start	5.23	Rating **	M	Issue No.	66
LM End	5.23	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.675244 °	37.675244 °
				-121.269287 °	-121.269287 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:22290 DS_ID:24058 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No permit identified for this crossing. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee at unknown depth below the crown. Siphon breaker in 10-inch steel riser on LS shoulder. FS Date: 9/10/2013					

Photo 1 of 3 : UCIP_SP_2017_22290_38020.jpg



Siphon breaker in 10-inch steel riser on LS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	5.23	Rating **	M	Issue No.	66 (cont)	
LM End	5.23	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			37.675244 °	37.675244 °	
				-121.269287 °	-121.269287 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:22290 DS_ID:24058 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No permit identified for this crossing. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee at unknown depth below the crown. Siphon breaker in 10-inch steel riser on LS shoulder. FS Date: 9/10/2013						

Photo 2 of 3 : UCIP_SP_2017_22290_38019.jpg



Cuts in pavement may indicate alignment of pipe at LS toe.

LM Start	5.23	Rating **	M	Issue No.	66 (cont)
LM End	5.23	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_SP_2017_22290_38018.jpg



Pipe visible at pond outlet off LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	5.24	Rating **	N	Issue No.	29
LM End	5.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.675099 °	37.675099 °
				-121.269264 °	-121.269264 °
DWR ID	DWR_RD2085_01_f_2015_29				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_113_29_20170407_00016.jpg



View of the tree stump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Reclamation District No. 2085 Kasson

Waterway			Bank	Unit Miles
Unit No. 02 San Joaquin River				0.70
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2017 - 4/20/2017			
DWR Inspector	Maksim Khashchuk			
Accompanied By	Ralph Timan RD2085			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River		0.70	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.02	Rating **	M	Issue No.	1
LM End	0.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.705050 °	37.713105 °
				-121.274587 °	-121.270091 °
DWR ID	DWR_RD2085_02_s_2017_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2017_RD2085_114_1_20170421_00001.jpg



View of the vegetation on the levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Reclamation District No. 2085 Kasson

Waterway			Bank	Unit Miles
Unit No. 03 San Joaquin River				0.29
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2017 - 4/20/2017			
DWR Inspector	Maksim Khashchuk			
Accompanied By	Ralph Timan RD2085			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 San Joaquin River		0.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.21	Rating **	U	Issue No.	1
LM End	0.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.682798 °	37.683052 °
				-121.262059 °	-121.261851 °
DWR ID	DWR_RD2085_03_s_2014_1				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion of the waterside levee slope has been observed. The erosion is about 3 feet tall vertical from the slope to the base of projected levee toe.					

LM Start	0.21	Rating **	U	Issue No.	1 (cont)
LM End	0.23	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : SP_2017_RD2085_115_1_20170421_00004.jpg



View of the erosion at the waterside levee toe. Spring 2017.

Photo 2 of 3 : SP_2017_RD2085_115_1_20170407_00001.jpg



View of the erosion at the waterside levee toe. Fall 2016.

LM Start	0.21	Rating **	U	Issue No.	1 (cont)
LM End	0.23	Issue Type +	Ma	Location *	WS

Photo 3 of 3 : SP_2017_RD2085_115_1_20170407_00002.jpg



View of the erosion at the waterside levee toe.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 San Joaquin River		0.29	04/20/2017 04/20/2017	Maksim Khashchuk

LM Start	0.25	Rating **	C	Issue No.	7
LM End	0.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.683274 °	37.683274 °
				-121.261839 °	-121.261839 °
DWR ID	DWR_RD2085_03_f _ 2016_7				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---